	10							
Test Procedure/Task: Rev: Issue: Title:	DWP#:	WO #:			Test Date/Time: 04/09/09			
Site/Program: CCAFS/Delta II	Location: Battery Lab - DII	Mission:	STSS_BL 0	OCK_201	Effectivity:			
Creator: Dehestani, Nahid Work Group: Engineering Electr Phone: 321-853-5235			Shift: 1 Note Created: 04/09/09 Note Updated:					
Title of Test: STSS Bloc	k 2010 Battery Processing							
	Desc	ription of Test						
Due to unplanned fire alarm event around 11:00 AM today, charging operation was interrupted manually for 40-0396 (1sys1) and 40-0398 (2sys1) Generated Test Variation DCl's 142163 (M593-DCl 3) and 142168 (M595-DCl 2) Restarted charge operation on the noted batteries in the afternoon (13:30) Completed "Step 2 Charge" on 1st stg batteries; Total Amp-Hour input were: 40-0396 (1sys1) ~ 9.33 AH (step 1) + 2.74 (step 2) = 12.07 AH 40-0397 (1sys2) ~ 8.11 AH (step 1) + 4.49 (step 2) = 12.60 AH Ref: M593 and M594, R39, Task 1 Completed "Step 1 Charge" on 2nd stg batteries; Amp-Hour input are: 40-0398 (2sys1) ~ 146 minutes @ 3.5 amps = 8.52 Amp-Hours 40-0399 (2sys2) ~ 128 minutes @ 3.5 amps = 7.47 Amp-Hours								
Ref: M595 and M590, R3								
Hours: 8								
	A	tachments	- 20					

Test Procedure/Task: LPD-V015 T2

Rev: **79** Issue: **1**

1 DWP #: 138630

WO #:

Test Date/Time: 04/09/09 0630

Title: Guidance Control Qualifications Non-DMCO

Site/Program: Location: Launch Pad (SLC2) Mission: STSS_BLOCK_201 Effectivity:

VAFB/Delta II

Work Group: Operations

Shift: 1 Note Started: 04/09/09 1124

Phone: 805-606-6340 x2318/6

Creator: McCarty, Mike

<u></u>	Title of Tests TC Notes: W4FT2 Cuidenes Control Cuide									
Title of	Title of Test: TC Notes: V15T2 Guidance Control Quals									
Description of Test										
Time 0630	H/A	Description ALCS turn on in work								
0700		Pretest briefing. Comm ch 5 for V15T2; V13T1 ch 6 and ch 7 for SC equipment hoist								
0750		Fire alarm in RLCC - personnel clearing RLCC- vehicle is powered SS TM; RIFCA turn on in work								
0810		Cleared to return to RLCC following fire alarm activated by security police for exercise. Proceeding with vehicle power up - no unexpected vehicle alarms.								
0815		Pad status amber for hoist.								
0830		FS/ SS TM powered; RIFCA power up in work. Items 2-16 are complete. Picking up with item 17 FS He system and N2 preps								
0835		Complete with item 17; proceeding with item 18 Engine Box Relay Box test								
0850		Complete thru item 18; continuing with item 19 Redundant MECO FIPS Verification								
0930		Complete with item 19								
1020		Continuing with item 21 FLSS Verification .								
1022		Complete with item 21 continuing with item 22 FLSS MECO Enable verifications								
1034		Item 25 FS P&C Redundancy cks in work								
1037		Item 25 complete; proceeding with Item 26 Ordnance Enable Arm cks in work								
1039		Item 26 complete. Item 27 VECO and Disarm checks in work								
1041		Items 23-24 Engine valve sequence securing and FIPS flex hose securing in work								
1102		Starting item 28; complete thru item 27 Range safety VECO and Disarm cks								
1130		Complete thru Item 28 CRD Single Point Arm Output checks								
1150		N2 bottle and LOX tank press in work for leak ck DCI VLCD DCI P3015								
1240		SS Control System Internal Redundancy cks in work								
1255	,	Item 33 Static Navigation test in work. V13T1 facility preps complete. Anomolous condition exists with guidance air. Further details not available. Uncertain if guidance air will be available to support V13T1								
1325		Complete thru Item 35; item 36 Quick Sequence with Ord Arm Bus off in work								
1412		Item 37 Normal Quick Sequence Test in work								
1447		Item 37 complete; Item 38 Min All Fire Sequence test in work								
1511		Complete thru item 38 awaiting shift change for item 39 Minimum All fire Cross Bus Test								
1543		Complete with item 39 continuing with 40								
1555		Complete with item 40 Minimum all Fire RACS test. Item 41 Min all fire securing in work								
1557		Item 43 SS N2 System Venting in work								
1625		Vehicle power securing complete								

Time	H/A	Description
1632		ALCS securing in work
1645		ALCS securing complete
CCN: Hours:		

Test Procedure/Task:	LPD-V02	23 T5					Test Date/Time:
Rev: 80 Is	sue: 1	DWP #:	124159	WO #:			04/09/09 1100
Title: Solid Motor Gr	ain Insp	ection					
Site/Program: VAFB/Delta II	Loc	ation: Launch	Pad (SLC2)	Mission	STSS_BL 0	OCK_201	Effectivity:
Creator: Neal, Jeffrey Phone: 805-606-6340	x2418	Work Group:	Engineering	Propulsion	Shift: 1	Note Cre	eated: 04/09/09 1701 dated:
Title of Test: SRM n	ozzle so	lvent wipes				· · · · · · · · · · · · · · · · · · ·	
			Descript	tion of Test			
Pre-spacecraft erec No new indications indications.					viously de	tected and	l documented
CCN: WDK2LVTL- Hours: 2	0						
		Mary Agent	Attac	hments			

Test Notes									
Test Procedure/Task: Rev: Issue: Title:	DWP #:	WO #:		Test Date/Time: 04/09/09 1530					
Site/Program: Local VAFB/Delta II	ation: Launch Pad (SLC2)	Mission:	Effe	ectivity:					
Creator: Hillier, Ed Work Group: Tech Services Group Shift: 1 Note Created: 04/09/09 1815 Phone: 805-606-6340 x2209 Note Updated:									
Title of Test: SLC-2 TSG FIRST SHIFT									
Description of Test									
MAINTENANCE SUPPOI ENVIRONMENTAL COM HYDRO LAB	TY CHECKSCOMPLETE RT & 7I WORK ORDERSACT PLIANCE / CAL LAB / LPD PARTS CTIVE AND ON GOING CHINE SHOP SUPPORTACT TES FOR PROOFLOAD AREA CHECKSCOMPLETE TURN-ON/TURN-OFFCOMPLETE CSYSTEM VERIFICATIONACTIVE MONITORING SY KOUTACTIVE MONITORING SY KOUTACTIVE, 2ND SHIFT COSES (ITEM 62-4)ACTIVE CONNEL ESCORTACTIVE CONNEL ESCORTACTIVE CONNEL ESCORT CRANE DRUM GOING COMPLETE COMPLETE, SEE ENG TO CK PREPSCOMPLETE CHAFCOMPLETE CHAPTOR TO S/C ERECTION COMPLETE CO	PULL SUPPOR' FIVE WITH MISO LETE, 2ND SHIFT ACTIVE STEM WHICH IS WILL ROS ETE A/R, 2ND SHIFT EAR ALIGNMEN ECKCOMF -COMPLETE EST NOTES (KE PRESS HELIUM COMPLETE	TACTIVE AND AIR SERVICE	SHOP ITEMS,					
Tiours.	AH								
	Attachments								

Test Procedure/Task: LPD	D-V132 T4		***************************************			Test Date/Time	<u>-</u>		
Rev: 17 Issue		124163	WO #:			04/09/09	•		
Title: S/C Mate (To Paylo									
Site/Program: VAFB/Delta II	Location: Payload Facility	•	Mission:	STSS_BL	OCK_201	Effectivity:			
Creator: Kelman, Sam	Work Group:	Engineering Mecha	nical	Shift: 1	Note Cre	eated: 04/09/09 1848	3		
Phone: 805-606-6340 x2	229/6				Note Upo	dated:			
Title of Test: S/C Mate 1	Title of Test: S/C Mate To PAF								
		Description of T	est						
Completed mate of S/C	Completed mate of S/C to the PAF. All four bolts are at flight tension.								
Fantastic job by the joi tensioning.	nt crews, thanks fo	or working through t	ne norma	l lunch bre	ak to com	plete final			
CCN: Hours:									
		Attachments							

		-			
Test Procedure/Task: DCI Rev: Issue: Title: Ordnance Resistan	2111 //	WO #:			Test Date/Time: 04/09/09
Site/Program: VAFB/Delta II	Location: Launch Pad (SLC2)	Mission:	STSS_BL 0	OCK_201	Effectivity:
Creator: Grahek, Mike Phone: 805-606-6340 x21	Work Group: Engineering Ele	ectrical	Shift: 1	Note Cre	eated: 04/09/09 1852 dated:
Title of Test: Trouble Sh	oot ADOTS P244 High Measureme	nt			
	Description	of Test			
vehicle Ord circuit, SST program file is set for a -Conclusion: Vehicle resresistance than ADOTS	oting on P244 SM FL IGN channel. RD limit is 3.53 ohms. Measured re 0.130 ohm cable resistance. sistance verified good at 3.4 ohms program file is set for. Will need to date continue trouble shooting to	esistance of A , problem is in o either revise	DOTS cate GSE ADO ADOTS s	ole is 0.503 OTS cable, oftware for	ohms, ADOTS , it has a higher r higher cable
cable. DCI may be trans	ferred to VACD for final disposition	n.		resistant	E III ADO13
CCN: WDK2LVTA Hours: 1					
The second second	Attachm	ents			

		,						
Test Procedure/Task: Rev: Issue Title: V15T2	: DWP #:	WO #:			Test Date/Time: 04/09/09 0700			
Site/Program: VAFB/Delta II	Location: Launch Pad (SLC2)	Mission:	STSS_BL	OCK_201	Effectivity:			
Creator: LeVey, Dale Phone: 321-476-3006	Work Group: Engineering	Work Group: Engineering Electrical		Note Created: 04/09/09 2004 Note Updated:				
Title of Test: Guidance and Control Qualification Non DMCO								
	Descrip	tion of Test						
resistance on P244 SM check. Performed troub Had 20 min delay due to	ew problems noted. Had reoccu GD SEP circuit. Did not have fa Dieshooting, see V15T1 DCI 6 tes o RLCC fire alarm. Noted severa s remove in supprt of V12T2	ilure in the prete st note. Supporte	st check, I ed LOX tar	out did in t ik leak che	he post test ck during lunch.			
CCN:								
Hours:								
	Attac	chments						
1								

Test Procedure/Task: Rev: Issue: Title:	DWP#:	WO #:	Test Date/Time: 04/09/09					
Site/Program: Decatur/Delta II	Location: Delta II Booster Checko (D2FSCO)	out Mission: WorldView	w-2 Effectivity: 20146					
Creator: Ettleman, Mike Phone: 256-432-1312	Work Group: Engineering	Shift: 1	Note Created: 04/09/09 0726 Note Updated:					
Title of Test: Worldview	2 Fuel float switch							
	Description of Test							
The Worldview 2 fuel float switch was successfully replaced. Leak check of the new assembly will start Friday.								
CCN: Hours:								
	Attachi	ments						